

View of existing house from neighboring rear yard.




View of Yacht Club Drive from existing rear stone porch.



View of gap between existing home and neighbor.

View of front of existing home from Frazier Drive.





View of front of existing home from Frazier Drive in relation to neighboring property.





View of existing house from rear yard.



