Project Description:	The existing awnings were deteriorating and created a safety hazard. New Awnings are to be places in the same location as existing ones. Existing light fixtures under awnings are to remain in place and will be replaced at a later time during the renovation. The exterior of the house is to be painted, old caulking & glue to be removed and masonry issues to be fixed before. New awnings to be in grey with a clear cover material. Awnings will be bolted into masonry wall										
											A X O N BUILDERS
											Axon Builders 1720 Spring Rd Cleveland, OH 4410
Elevations:											
											nd Properties Replacement
											Southber Awning F
North Elevation						West E	levation				
											PROJECT ADDRESS: 21045 Southbend Circ Rocky River, OH 4411
South Elevation						East E	evation				ISSUE DATE: 03/06/2024 SHEET NAME Elevations
											1/2

