



BUILDING A
EXISTING EXTERIOR CONDITIONS

NTS



BUILDING A EXISTING EXTERIOR CONDITIONS



BUILDING A
EXISTING EXTERIOR CONDITIONS

NTS



BUILDING A
EXISTING EXTERIOR CONDITIONS
A102) NTS



BUILDING A
EXISTING EXTERIOR CONDITIONS

NTS



BUILDING A

TO EXISTING EXTERIOR CONDITIONS

A1022 NTS



BUILDING A

8 PROPOSED SIGNAGE RENDERING

A102 NTS

Slate Office

3100 Wooster Ave. Rocky River, OH 44116

SLATE


INTERIORS STUDIO


17415 Northwood Ave. Suite 201 Lakewood, Ohio 44107 T. 216 505 0341

E. bridget@slate-interiors.com W. www.slate-interiors.com

Exterior Updates

A102







BUILDING B EXISTING EXTERIOR CONDITIONS

Building B: exterior walls, window trim, door, and fascia board painted PT-1 on all 4 sides of building.

PT-1: Sherwin Williams Iron Ore 7069



Building B: exterior walls, window trim, door, underside of soffits, and fascia board painted PT-1 on all 4 sides of


PT-1: Sherwin Williams Iron Ore 7069



No changes to existing exterior architecture.

– New signage. "Slate Interiors Studio" in protruding block letters. Color: white.





INTERIORS STUDIO

17415 Northwood Ave. Suite 201 Lakewood, Ohio 44107 T. 216 505 0341 E. bridget@slate-interiors.com W.www.slate-interiors.com

Slate Office

3100 Wooster Ave. Rocky River, OH 44116

Exterior Updates